



INTERNATIONAL STANDARD ISO/IEC 12139-1:2009
TECHNICAL CORRIGENDUM 1

Published 2010-02-01

INTERNATIONAL ORGANIZATION FOR STANDARDIZATION • МЕЖДУНАРОДНАЯ ОРГАНИЗАЦИЯ ПО СТАНДАРТИЗАЦИИ • ORGANISATION INTERNATIONALE DE NORMALISATION
INTERNATIONAL ELECTROTECHNICAL COMMISSION • МЕЖДУНАРОДНАЯ ЭЛЕКТРОТЕХНИЧЕСКАЯ КОМИССИЯ • COMMISSION ÉLECTROTECHNIQUE INTERNATIONALE

Information technology — Telecommunications and information exchange between systems — Powerline communication (PLC) — High speed PLC medium access control (MAC) and physical layer (PHY) —

**Part 1:
General requirements**

TECHNICAL CORRIGENDUM 1

Technologies de l'information — Télécommunications et échange d'information entre systèmes — Courants porteurs en ligne (PLC) — Contrôle d'accès au support (MAC) et couche physique (PHY) par PLC à grande vitesse —

Partie 1: Exigences générales

RECTIFICATIF TECHNIQUE 1

Technical Corrigendum 1 to ISO/IEC 12139-1:2009 was prepared by Joint Technical Committee ISO/IEC JTC 1, *Information technology*, Subcommittee SC 6, *Telecommunications and information exchange between systems*.

Page 10, Clause 6

Insert the following immediately below the Clause 6 title:

CAUTION — Simultaneous use of ISO/IEC 12139-1 and non-ISO/IEC 12139-1 PLC devices in proximity, operating in the overlapping frequency band, can cause interference between them.

ICS 35.110

Ref. No. ISO/IEC 12139-1:2009/Cor.1:2010(E)

© ISO/IEC 2010 – All rights reserved

Published in Switzerland