

# TECHNICAL REPORT

# IEC TR 61400-24

First edition  
2002-07

---

---

## Wind turbine generator systems –

### Part 24: Lightning protection



Reference number  
IEC/TR 61400-24:2002(E)

## Publication numbering

As from 1 January 1997 all IEC publications are issued with a designation in the 60000 series. For example, IEC 34-1 is now referred to as IEC 60034-1.

## Consolidated editions

The IEC is now publishing consolidated versions of its publications. For example, edition numbers 1.0, 1.1 and 1.2 refer, respectively, to the base publication, the base publication incorporating amendment 1 and the base publication incorporating amendments 1 and 2.

## Further information on IEC publications

The technical content of IEC publications is kept under constant review by the IEC, thus ensuring that the content reflects current technology. Information relating to this publication, including its validity, is available in the IEC Catalogue of publications (see below) in addition to new editions, amendments and corrigenda. Information on the subjects under consideration and work in progress undertaken by the technical committee which has prepared this publication, as well as the list of publications issued, is also available from the following:

- **IEC Web Site ([www.iec.ch](http://www.iec.ch))**
- **Catalogue of IEC publications**  
The on-line catalogue on the IEC web site ([www.iec.ch/catlg-e.htm](http://www.iec.ch/catlg-e.htm)) enables you to search by a variety of criteria including text searches, technical committees and date of publication. On-line information is also available on recently issued publications, withdrawn and replaced publications, as well as corrigenda.
- **IEC Just Published**  
This summary of recently issued publications ([www.iec.ch/JP.htm](http://www.iec.ch/JP.htm)) is also available by email. Please contact the Customer Service Centre (see below) for further information.
- **Customer Service Centre**  
If you have any questions regarding this publication or need further assistance, please contact the Customer Service Centre:

Email: [custserv@iec.ch](mailto:custserv@iec.ch)  
Tel: +41 22 919 02 11  
Fax: +41 22 919 03 00

# TECHNICAL REPORT

# IEC TR 61400-24

First edition  
2002-07

---

---

## Wind turbine generator systems – Part 24: Lightning protection

© IEC 2002 — Copyright - all rights reserved

No part of this publication may be reproduced or utilized in any form or by any means, electronic or mechanical, including photocopying and microfilm, without permission in writing from the publisher.

International Electrotechnical Commission, 3, rue de Varembé, PO Box 131, CH-1211 Geneva 20, Switzerland  
Telephone: +41 22 919 02 11 Telefax: +41 22 919 03 00 E-mail: [inmail@iec.ch](mailto:inmail@iec.ch) Web: [www.iec.ch](http://www.iec.ch)



Commission Electrotechnique Internationale  
International Electrotechnical Commission  
Международная Электротехническая Комиссия

PRICE CODE **XB**

*For price, see current catalogue*

## CONTENTS

FOREWORD .....	5
INTRODUCTION .....	7
1 Scope .....	8
2 Definitions .....	8
3 Lightning and wind turbines .....	12
3.1 The properties of lightning .....	12
3.2 Lightning discharge formation and electrical parameters.....	12
3.3 Cloud-to-ground flashes.....	13
3.4 Upward initiated flashes.....	17
3.5 Lightning protection of wind turbines – the generic problem .....	19
3.6 Existing IEC standards and technical reports dealing with lightning protection .....	20
4 Damage statistics .....	21
4.1 Data on wind turbine lightning damage .....	21
4.2 Damage statistics .....	21
4.3 Database merits and weaknesses.....	27
4.4 Conclusions and recommendations.....	28
5 Evaluation of the risk of lightning damage to a wind turbine .....	29
5.1 Introduction .....	29
5.2 Assessing the lightning flash frequency to a wind turbine.....	29
5.3 Use of IEC 61024-1-1 .....	30
5.4 Use of IEC 61662 .....	32
5.5 Analysis of blade lightning protection system costs.....	34
5.6 Analysis of lightning protection costs for wind turbine control systems .....	35
6 Lightning protection of wind turbine blades .....	36
6.1 Blade structure .....	36
6.2 Blade damage mechanism .....	38
6.3 Lightning protection for wind turbine blades .....	38
6.4 Interception efficiency.....	40
6.5 Sizing of materials .....	41
6.6 Blade to hub connection .....	43
6.7 Carbon reinforced plastic (CRP) .....	43
6.8 Wiring inside blades .....	43
7 Protection of bearings and gearbox.....	44
7.1 Damage to bearings due to AC and DC currents .....	44
7.2 Damage to bearings due to lightning currents .....	44
7.3 Laboratory investigations .....	44
7.4 Lightning damage to gearbox.....	45
7.5 Lightning protection of bearings and gearbox elements.....	45
8 Protection of electrical and control system .....	46
8.1 Introduction .....	46
8.2 Configuration of electrical equipment.....	46
8.3 Lightning protection zones .....	50
8.4 Surge coupling mechanisms .....	52
8.5 Bonding and shielding .....	53

8.6	Surge protection .....	56
8.7	Summary .....	58
9	Earthing .....	58
9.1	Lightning protection system earth termination for a single wind turbine .....	58
9.2	Lightning protection system earth terminations in a wind farm .....	60
10	Personnel safety .....	61
10.1	General .....	61
11	Conclusions and recommendations for further work .....	62

Annex A	Typical lightning damage questionnaire .....	64
---------	--	----

Bibliography .....	66
--------------------	----

Figure 1	– Processes involved in the formation of a cloud-to-ground flash [4] .....	14
Figure 2	– Typical profile of a negative cloud-to-ground flash (not to scale) .....	15
Figure 3	– Typical profiles of negative cloud-to-ground flashes (not to scale) .....	16
Figure 4	– Typical profile of a positive cloud-to-ground flash .....	17
Figure 5	– Typical profile of a negative upward-initiated flash .....	17
Figure 6	– Different profiles of negative upward initiated flashes (not to scale) .....	18
Figure 7	– Faults by component (Germany) .....	23
Figure 8	– Faults by component (Denmark) .....	23
Figure 9	– Faults by component (Germany) .....	24
Figure 10	– Faults by component (Denmark) .....	24
Figure 11	– Repair costs by component and size (Germany) .....	25
Figure 12	– Average down time by component and size (Germany) .....	25
Figure 13	– Annual variation in lightning activity and damage (Denmark) .....	26
Figure 14	– Faults caused by lightning (Denmark 1990-1998) .....	26
Figure 15	– Lightning damage events (Germany 1991-1998) .....	27
Figure 16	– Equivalent collection area of the wind turbine .....	30
Figure 17	– Types of wind turbine blades .....	37
Figure 18	– Lightning protection for large modern wind turbine blades .....	39
Figure 19	– Alternative current path to reduce lightning current .....	46
Figure 20	– Principle configuration of electrical equipment in a grid-connected wind turbine .....	47
Figure 21	– Principle control system configuration .....	49
Figure 22	– Rolling sphere model .....	50
Figure 23	– Example of the division of the interior of a wind turbine into protection zones .....	51
Figure 24	– Differential and common mode coupling .....	53
Figure 25	– Two control cabinets located on different metallic planes inside a nacelle .....	54
Figure 26	– Magnetic coupling mechanism .....	55
Figure 27	– Example design of a combination type SPD .....	57
Figure 28	– Typical wind turbine earthing arrangement .....	59

Table 1 – Cloud-to-ground lightning current parameters .....	15
Table 2 – Upward initiated lightning current parameters .....	18
Table 3 – Standards and technical reports issued by IEC (Mid 2001) .....	20
Table 4 – IEC TC 81 work in progress (Mid 2001) .....	21
Table 5 – Lightning damage frequency .....	22
Table 6 – Regional effect on lightning damage (Germany) .....	22
Table 7 – Lightning fault summary (Sweden) .....	23
Table 8 – Energy and availability loss compared to other faults .....	26
Table 9 – Lightning protection system levels .....	31
Table 10 – Maximum values of lightning parameters corresponding to protection levels .....	32
Table 11 – Minimum dimensions of lightning protection system materials .....	41
Table 12 – Proposed minimum dimensions for lightning protection system materials .....	41
Table 13 – Physical characteristics of typical materials used in lightning protection systems .....	42
Table 14 – Temperature rise [K] for different conductors as a function of $W/R$ .....	42
Table 15 – Lightning protection zones .....	50
Table 16 – Examples of component requirements in given zones .....	52
Table 17 – Effect of various protection measures on screen transient voltages .....	56
Table 18 – Suitability of electrode types .....	60

## INTERNATIONAL ELECTROTECHNICAL COMMISSION

**WIND TURBINE GENERATOR SYSTEMS –****Part 24: Lightning protection**

## FOREWORD

- 1) The IEC (International Electrotechnical Commission) is a worldwide organization for standardization comprising all national electrotechnical committees (IEC National Committees). The object of the IEC is to promote international co-operation on all questions concerning standardization in the electrical and electronic fields. To this end and in addition to other activities, the IEC publishes International Standards. Their preparation is entrusted to technical committees; any IEC National Committee interested in the subject dealt with may participate in this preparatory work. International, governmental and non-governmental organizations liaising with the IEC also participate in this preparation. The IEC collaborates closely with the International Organization for Standardization (ISO) in accordance with conditions determined by agreement between the two organizations.
- 2) The formal decisions or agreements of the IEC on technical matters express, as nearly as possible, an international consensus of opinion on the relevant subjects since each technical committee has representation from all interested National Committees.
- 3) The documents produced have the form of recommendations for international use and are published in the form of standards, technical specifications, technical reports or guides and they are accepted by the National Committees in that sense.
- 4) In order to promote international unification, IEC National Committees undertake to apply IEC International Standards transparently to the maximum extent possible in their national and regional standards. Any divergence between the IEC Standard and the corresponding national or regional standard shall be clearly indicated in the latter.
- 5) The IEC provides no marking procedure to indicate its approval and cannot be rendered responsible for any equipment declared to be in conformity with one of its standards.
- 6) Attention is drawn to the possibility that some of the elements of this technical report may be the subject of patent rights. The IEC shall not be held responsible for identifying any or all such patent rights.

The main task of IEC technical committees is to prepare International Standards. However, a technical committee may propose the publication of a technical report when it has collected data of a different kind from that which is normally published as an International Standard, for example “state of the art”.

Technical reports do not necessarily have to be reviewed until the data they provide are considered to be no longer valid or useful by the maintenance team.

IEC 61400-24, which is a technical report, has been prepared by IEC technical committee 88: Wind turbine systems.

The text of this technical report is based on the following documents:

Enquiry draft	Report on voting
88/128/CDV	88/142/RVC

Full information on the voting for the approval of this technical report can be found in the report on voting indicated in the above table.

This publication has been drafted in accordance with the ISO/IEC Directives, Part 3.

This document, which is purely informative, is not to be regarded as an International Standard.

The committee has decided that the contents of this publication will remain unchanged until 2007. At this date, the publication will be either

- reconfirmed;
- withdrawn;
- replaced by a revised edition, or
- amended.

## INTRODUCTION

During the last few years damage to wind turbines due to lightning strokes has been recognized as an increasing problem. The increasing number and height of installed turbines have resulted in an incidence of lightning damage greater than anticipated with repair costs beyond acceptable levels. The influence of lightning faults on operational reliability becomes a concern as the capacity of individual wind turbines increases and turbines move offshore. This is particularly the case when several large wind turbines are operated together in wind farm installations since the potential loss of multiple large production units due to one lightning flash is unacceptable.

Unlike other electrical installations, such as overhead lines, substations and power plants, where protective conductors can be arranged around or above the installation in question, wind turbines pose a different lightning protection problem due to their physical size and nature. Wind turbines typically have two or three blades with a diameter up to 100 m or more rotating 100 m above the ground. In addition, there is extensive use of insulating composite materials, such as glass fibre reinforced plastic, as load-carrying parts. The lightning protection system has to be fully integrated into the different parts of the wind turbines to ensure that all parts likely to be lightning attachment points are able to withstand the impact of the lightning and that the lightning current may be conducted safely from the attachment points to the ground without unacceptable damage or disturbances to the systems.

To that end this report was developed to inform designers, purchasers, operators, certification agencies and installers of wind turbines on the state-of-the-art of lightning protection of wind turbines.